

Weidmüller Remote IO Release

Notes

V1.0.0

- Initial version.

V1.0.1

- Fixed bug with setting property value when Weidmüller Remote IO component is inside the locked subsystem.

V1.0.2

- Added option to select Ethernet port of HIL device which will be used. This option is available only on THCC 2025.3 or higher.
- Component help document modified.
- All properties related to Modbus settings are now under *Modbus* tab.